

PCS7 V10 Compatibility

This application note guides the user to migrate and resolve errors in PCS7 V10.1 SP1 where CTEU_PCS7 and CPX_PCS7 libraries are installed.

CTEU, CPX,
PCS7_V10.1

TitlePCS7 V10 Compatibility
Version 1.10
Document no. 100802
Originalen
AuthorFesto

Last saved 20.01.2026

General information:

This document is intended for qualified, trained and instructed professionals. The data provided in this document are no guaranteed specifications, in particular with regard to functionality, condition or quality in the legal sense. The information in this document is intended only as simple indications for the implementation of a specific, hypothetical application, and in no way as a substitute for the operating instructions of the respective manufacturers or the design and testing of the respective application by the user. The respective operating instructions for Festo products can be found under www.festo.com. The user of this document must ensure that each function described herein works properly in his application. The user remains solely responsible for his or her own use of this document, even by studying this document and using the information mentioned therein. This also applies to any software (in source code and/or object code) that is made available to the user as an appendix to this document.

Rights of use of the software:

If software is made available to the user as an appendix to this document, the user is granted a simple and unlimited right of use hereto. This right also includes the processing and distribution of the software to third parties in edited or unedited form. The User is not permitted to use the name "Festo" to endorse or promote products derived from the Software without express prior written permission.

Software is provided to the user "as is". Festo does not assume any warranty or guarantee with regard to software. Festo's liability for damages of any kind arising from the use of the software is limited to intent and gross negligence.

Legal Notices:

©Festo SE & Co. KG, all rights reserved. A change in content and form is only permitted with the express written consent of Festo SE & Co. KG. Festo grants the user the right to reproduce this document in a form that remains unchanged in terms of content and form and to pass it on to third parties.

Table of contents

- 1 Introduction 5**
- 1.1 Summary 5
- 1.2 Affected modules 5

- 2 CTEU-PB/ CTEU-PB-EX1C 6**
- 2.1 Topology 6
- 2.2 Hardware Configuration 6
- 2.3 Software Compilation 7

- 3 CPX-FB13 12**
- 3.1 Topology 12
- 3.2 Hardware Configuration 12
- 3.3 Software Compilation 13

1 Introduction

1.1 Summary

The libraries CTEU_PCS7 and CPX_PCS7 integrates CTEU and CPX fieldbus nodes to PCS7 system and gives function blocks and operator messages for diagnostics. The current version of libraries CTEU_PCS7 (V1.0.1.3) and CPX_PCS7 (V2.2.0.4) support PCS7 V9.1SP2. For PCS7 V10 and above, small modifications need to be done if the libraries need to be used in projects. The aim of this application note is to provide steps to user which help in making the small modifications necessary for migrating the existing library to PCS7 V10 and solving compilation errors encountered in the process.

1.2 Affected modules

It is seen that the libraries **work properly for Profinet terminals**.

Ex: for CTEU: CTEU_PN and CTEU_PN_EX1C
for CPX_PCS7: FB 43, 44.

No compilation errors should occur when downloading to AS. Also all OS messages should be working fine.


However, when a **Profibus terminal** is configured, **compilation errors** are found.

Ex: for CTEU: CTEU_PB and CTEU_PB_EX1C
for CPX_PCS7: FB13.

This application note indicates the steps to be followed to integrate Profibus terminals by clearing compilation errors. The fix to these modules will be released in the upcoming version of individual libraries. This application note provides a temporary workaround.


2 CTEU-PB/ CTEU-PB-EX1C

2.1 Topology




2.2 Hardware Configuration

For this example, we are considering a CTEU-PB connected and a 16 DO (VAEM-L1-S-8-PT) as shown below.




2.3 Software Compilation


Add channel function blocks from the library and assign output addresses to the correct parameters as shown:




1. Start compilation
2. Set Diagnostic messages as Enable all.
3. Set Diagnostic Blocks for Operator C and M as Set all.
4. Select the PCS7BasisLibraryV100.
5. Select OK.



After compilation, the message below is displayed with an error:




We can see that the source of the error is DP_SL_DIAG from OB_DIAG1 block is not connected with source signal.




We can also see that the parameter DP_SL_DIAG is not even visible in CFC. The fix is to make DP_SL_DIAG visible and the error cleared follow the steps below:

1. Right click on function block OB_DIAG1
2. Select Object Properties.




3. Left click on I/Os.
4. Scroll down till we see DP_SL_DIAG.
5. Scroll to Invisible tab and uncheck.
6. Left click on OK.




Now the same steps are to be followed for DP_SL_DIAG_OUT to become visible.


1. Right click on function block OB_DIAG1
2. Select Object Properties.
3. Left click on I/Os.
4. Scroll down till we see DP_SL_DIAG_OUT.
5. Scroll to Invisible tab and uncheck.
6. Left click on OK.



After this step DP_SL_DIAG and DP_SL_DIAG_OUT should become visible. The next step is to interconnect these two parameters which will resolve the compilation error.




Once the connection is made like the figure shown above, start the compilation once more. After compilation we can see that the errors are resolved and download to AS is possible.



3 CPX-FB13

3.1 Topology




3.2 Hardware Configuration

For this example, we are considering a CPX-FB13 connected as shown below.


Slot	DP ID	Order Number / Designation	I Address	Q Address	Comment
1	0	CPX-FB13 DP-Slave			
2	80I	CPX-8DE (8DI)	0		
3	80I	CPX-8DE-D (8DI-D)	1		
4	80I	CPX-4DE (4DI)x2	2		
5	8D0	CPX-8DA (8DO)		0	
6	8D0	CPX-4DA (4DO)x2		1	
7	8DX	CPX-8DE-8DA (8DI/8DO)	3	2	
8	80I	CPX-8NDE (8NDI)	4		
9					

3.3 Software Compilation


Add channel function blocks from the library and assign output addresses to the correct parameters as shown:




1. Start compilation
2. Set Diagnostic messages as Enable all.
3. Set Diagnostic Blocks for Operator C and M as Set all.
4. Select the PCS7BasisLibraryV100.
5. Select OK.



6. After compilation, the message below is displayed with an error:




We can see that the source of the error is DP_SL_DIAG from OB_DIAG1 block is not connected with source signal.




We can also see that the parameter DP_SL_DIAG is not even visible in CFC. The fix is to make DP_SL_DIAG visible and the error cleared follow the steps below:

1. Right click on function block OB_DIAG1
2. Select Object Properties.




3. Left click on I/Os.
4. Scroll down till we see DP_SL_DIAG.
5. Scroll to Invisible tab and uncheck.
6. Left click on OK.




Same steps are to be followed for DP_SL_DIAG_OUT to become visible.

1. Right click on function block OB_DIAG1
2. Select Object Properties.
3. Left click on I/Os.
4. Scroll down till we see DP_SL_DIAG_OUT.
5. Scroll to Invisible tab and uncheck.
6. Left click on OK.



After this step DP_SL_DIAG and DP_SL_DIAG_OUT should become visible. The next step is to interconnect these two parameters which will resolve the compilation error.



Once the connection is made like the figure shown above, start the compilation once more. After compilation we can see that the errors are resolved and download to AS is possible.

