



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

PR Project name: 100402

Project file name:	C:\Users\jkh\Documents\Projects\20220131-002\100402 Sistema Project - V3.0.4 - EN.ssm
Creation date:	14.12.2021 08:17:10
Project status:	
Project number:	
Project version:	
Authors:	
Project managers:	
Inspectors:	
Dangerous point/machine:	
Documentation:	
Document:	
Version of software:	3.0.4 build 3
Version of standard:	ISO 13849-1:2023, ISO 13849-2:2012
Checksum:	42d2f621bc647e349fee673a2973a282
Options:	☒ Use DC intermediate levels for calculation of PFH (more precise) ☒ MTTFD capping for category 4 lower from 2500 to 100 years.
Status:	☒ green
Note:	There are no warnings listed for this project (or it's subordinate basic elements).

Print options

- | | |
|--|---|
| ☒ Show device details | ☒ Show requirements on PL and Category |
| ☒ Show documentations on SF, SB, BL and EL | ☒ Show parameter documentations on PLr, PL, Category, CCF, MTTFD and DC |
| ☐ Show CCF and DC measures in detail | ☒ Show messages |

Contained safety functions**SF** Name: STO

Required: PLr c	Reached: PL c	PFH [1/h]: 1,15E-6	Status: green
-----------------	---------------	--------------------	---------------

List of documented messages:

- No messages known -

List of devices with a permissible operation time (T10D) of less than 20 years:

- No devices known -

SF Name: PUS (operation pressure)

Required: PLr d	Reached: PL e	PFH [1/h]: 4,29E-8	Status: green
-----------------	---------------	--------------------	---------------



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

PR Project name: 100402

List of documented messages:

- No messages known -

List of devices with a permissible operation time (T10D) of less than 20 years:

- No devices known -

SF Name: PUS (pilot pressure)

Required: PLr d

Reached: PL d

PFH [1/h]: 4,29E-8

Status: green

List of documented messages:

- No messages known -

List of devices with a permissible operation time (T10D) of less than 20 years:

- No devices known -



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: STO

Identifier of the Safety function:

Safety function type:

Triggering event:

Reaction and
Behaviour on power failure:

Safe state:

Operation mode:

Interfaces:

Demand rate:

Running-on time:

Priority:

Documentation:

Document:


Required Performance Level Safety function

PLr (by risk graph): c

Severity of injury (S): Serious (normally irreversible) injury or death

Frequency / exposure times to hazard (F): Seldom to less often / exposure time is short

Possibility of avoiding (P): Possible under specific conditions

Risk graph: 

Documentation:

Document:

Performance Level Safety function

Reached PL: c PFH [1/h]: 1,15E-6

Electromagnetic immunity, EMI (Annex L) Safety function


Route for fulfilment
of EMI measures: n/a

Documentation:

Document:

List of devices with a permissible operation time (T10D) of less than 20 years:

Device list:



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: STO

Status / Messages Safety function

Status: green

Subsystems (1 / 1)

SB Name: Output

Reference designator:

Inventory number:

Device details Subsystem

Device Manufacturer:

Device Identifier:

Device group:

Part number:

Revision:

Function: ☐ Input ☐ Logic ☐ Output ☒ unknown

Use case:

Description of the use case:

Documentation Subsystem

Documentation:

Document:

Performance Level Subsystem

PL determination: Determine PL/PFH from Category, MTTFD and DCavg

Qualitative aspects (e.g. software, see sections 7, 10.3) Subsystem

Qualitative aspects suitable up to PL: n/a

Documentation:

Document:

Electromagnetic immunity, EMI (Annex L) Subsystem

Route for fulfilment of EMI measures: The fulfilment of the measures for electromagnetic immunity (EMI) was documented in the associated safety function.

PL requirements: fulfilled

The PL shall be determined by the estimation of the following aspects (section 6.1.1):

- Behaviour of the safety function under fault conditions [fulfilled]
- Safety-related software according to clause 7 and Annex J or no software included [fulfilled]
- Systematic failure (see clause 6.1.7 and Annex G) [fulfilled]
- Ability to perform a safety function under expected environmental conditions [fulfilled]



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: STO

Reached PL:	c	PFH [1/h]:	1,15E-6
-------------	---	------------	---------

Documentation:*Category Subsystem*

Cat.:	1
-------	---

Category requirements:	fulfilled
------------------------	-----------

Requirements for the category:

- Accordance with relevant standards to withstand the expected influences. [fulfilled]
- Basic safety principles are being used. [fulfilled]
- Well-tried components (clause 6.1.11) are being used. [fulfilled]
- Well-tried safety principles are being used. [fulfilled]
- MTTFD is at least High. [fulfilled]

Documentation:**Source (e.g. standard) Category:****File:***MTTFD and Mission time Subsystem*

MTTFD [a]:	100 (High)
------------	------------

Mission time [a]:	20	Shortest mission time [a]:	20
-------------------	----	----------------------------	----

Status / Messages Subsystem

Status:	green
---------	-------


Channels / Test channels (1 / 1)**CH** Name: Channel 1

MTTFD [a]: 100

Blocks (1 / 1)**BL** Name: 5/3 Directional control valve

Reference designator:	Q2
-----------------------	----

Inventory number:*Device details Block***Device Manufacturer:****Device Identifier:****Device group:****Part number:****Revision:****Function:**☐ Input
☒ Output☐ Logic
☐ unknown



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: STO

Technology: unknown

Category: -

Use case:

Description of the use case:

Documentation Block

Documentation:

Document:

MTTFD and Mission time Block

MTTFD [a]: 380,5 (High)

Mission time [a]: 20

Shortest mission time [a]: 20

B10 [cycles]: 10000000

RDF [%]: 50

B10D [cycles]: 20000000

nop [cycles/a]: 525600

Documentation:

Document:

Status / Messages Block

Status: green

SF Safety function: PUS (operation pressure)

Identifier of the Safety function:

Safety function type:

Triggering event:

Reaction and Behaviour on power failure:

Safe state:

Operation mode:

Interfaces:

Demand rate:

Running-on time:

Priority:

Documentation:

Document:




Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

Safety function: PUS (operation pressure)

Required Performance Level Safety function

PLr (by risk graph):	d
Severity of injury (S):	Serious (normally irreversible) injury or death
Frequency / exposure times to hazard (F):	Frequent to continuous / exposure time is long
Possibility of avoiding (P):	Possible under specific conditions
Risk graph:	

Documentation:

Document:

Performance Level Safety function

Reached PL:	e	PFH [1/h]:	4,29E-8
-------------	---	------------	---------

Electromagnetic immunity, EMI (Annex L) Safety function

Route for fulfilment of EMI measures:	n/a
Documentation:	
Document:	

List of devices with a permissible operation time (T10D) of less than 20 years:

Device list:	
--------------	--

Status / Messages Safety function

Status:	green
---------	-------

Subsystems (1 / 1)

 Name: Output	
Reference designator:	
Inventory number:	
Device details Subsystem	
Device Manufacturer:	
Device Identifier:	
Device group:	
Part number:	
Revision:	
Function:	☐ Input ☒ Output ☐ Logic ☐ unknown



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (operation pressure)

Use case:

Description of the use case:

Documentation Subsystem

Documentation:

Document:

Performance Level Subsystem

PL determination: Determine PL/PFH from Category, MTTFD and DCavg

Qualitative aspects (e.g. software, see sections 7, 10.3) Subsystem

Qualitative aspects suitable up to PL: n/a

Documentation:

Document:

Electromagnetic immunity, EMI (Annex L) Subsystem

Route for fulfilment of EMI measures: The fulfilment of the measures for electromagnetic immunity (EMI) was documented in the associated safety function.

PL requirements: fulfilled

The PL shall be determined by the estimation of the following aspects (section 6.1.1):

- Behaviour of the safety function under fault conditions [fulfilled]
- Safety-related software according to clause 7 and Annex J or no software included [fulfilled]
- Systematic failure (see clause 6.1.7 and Annex G) [fulfilled]
- Ability to perform a safety function under expected environmental conditions [fulfilled]

Reached PL: e PFH [1/h]: 4,29E-8

Documentation:

Category Subsystem

Cat.: 3

Category requirements: fulfilled

Requirements for the category:

- Accordance with relevant standards to withstand the expected influences. [fulfilled]
- Basic safety principles are being used. [fulfilled]
- Well-tried safety principles are being used. [fulfilled]
- A single fault tolerance and reasonable fault detection are given. [fulfilled]
- MTTFD is at least Low. [fulfilled]
- Requirement fulfilled because of the assumed limit value accuracy of 5 percentage points. [fulfilled]
- The achieved score of the CCF-rating is at least 65. [fulfilled]

Documentation:



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (operation pressure)

Source (e.g. standard) Category:

File:

MTTFD and Mission time Subsystem

MTTFD [a]: 100 (High)

Mission time [a]: 20

Shortest
mission time [a]: 20*Diagnostic coverage Subsystem*

DCavg [%]: 90 (Medium)

Common cause failure Subsystem

CCF Points: 95 (fulfilled)

CCF Measures:

- 15 Points | Separation/segregation
- 20 Points | Diversity
- 15 Points | Protection against over-voltage, over-pressure, over-current, over-temperature
- 5 Points | Assessment/analysis
- 5 Points | Training
- 25 Points | Prevention of EMI or impurity of fluidic medium
- 10 Points | Other influences

Documentation:

Document:

Status / Messages Subsystem

Status: green

Channels / Test channels (1 / 2)**CH** Name: Channel 1

MTTFD [a]: 100

Blocks (1 / 1)**BL** Name: 5/3 Directional control valve

Reference designator: Q2

Inventory number:

Device details Block

Device Manufacturer:

Device Identifier:

Device group:

Part number:

Revision:



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (operation pressure)

Function:	☐ Input ☒ Output	☐ Logic ☐ unknown
Technology:	unknown	
Category:	-	
Use case:		
Description of the use case:		

Documentation Block

Documentation:
Document:

MTTFD and Mission time Block

MTTFD [a]:	380,5 (High)		
Mission time [a]:	20	Shortest mission time [a]:	20
B10 [cycles]:	10000000	RDF [%]:	50
B10D [cycles]:	20000000	nop [cycles/a]:	525600
Documentation:			
Document:			

Diagnostic coverage Block

DC [%]:	90 (Medium)
Measure:	Indirect monitoring (e.g. monitoring by pressure switch, electrical position monitoring of machine actuators)
Documentation:	
Document:	


Status / Messages Block

Status:	green
----------------	-------

Channels / Test channels (2 / 2)**CH** Name: Channel 2

MTTFD [a]: 100

Blocks (1 / 1)**BL** Name: 3/2 Directional control valve**Reference designator:** Q1**Inventory number:**



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (operation pressure)*Device details Block*

Device Manufacturer:

Device Identifier:

Device group:

Part number:

Revision:

Function:

☐ Input
☒ Output☐ Logic
☐ unknown

Technology:

unknown

Category:

-

Use case:

Description of the use case:

Documentation Block

Documentation:

Document:

MTTFD and Mission time Block

MTTFD [a]: 91324,2 (High)

Mission time [a]: 20

Shortest
mission time [a]: 20

B10 [cycles]: 10000000

RDF [%]: 50

B10D [cycles]: 20000000

nop [cycles/a]: 2190

Documentation:

Document:

Diagnostic coverage Block

DC [%]: 90 (Medium)

Measure:

Indirect monitoring (e.g. monitoring by pressure switch, electrical position monitoring of machine actuators)

Documentation:

Document:

Status / Messages Block

Status: green

SF Safety function: PUS (pilot pressure)



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (pilot pressure)

Identifier of the Safety function:

Safety function type:

Triggering event:

Reaction and
Behaviour on power failure:

Safe state:

Operation mode:

Interfaces:

Demand rate:

Running-on time:

Priority:

Documentation:

Document:

Required Performance Level Safety function


PLr (by risk graph): d

Severity of injury (S): Serious (normally irreversible) injury or death

Frequency / exposure times to hazard (F): Frequent to continuous / exposure time is long

Possibility of avoiding (P): Possible under specific conditions

Risk graph:



Documentation:

Document:

Performance Level Safety function

Reached PL: d

PFH [1/h]: 4,29E-8

Electromagnetic immunity, EMI (Annex L) Safety function

Route for fulfilment
of EMI measures: n/a

Documentation:

Document:

List of devices with a permissible operation time (T10D) of less than 20 years:

Device list:



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (pilot pressure)

Status / Messages Safety function

Status: green

Subsystems (1 / 2)

SB Name: Output

Reference designator:

Inventory number:

Device details Subsystem

Device Manufacturer:

Device Identifier:

Device group:

Part number:

Revision:

Function: ☐ Input ☐ Logic ☒ Output ☐ unknown

Use case:

Description of the use case:

Documentation Subsystem

Documentation:

Document:

Performance Level Subsystem

PL determination: Determine PL/PFH from Category, MTTFD and DCavg

Qualitative aspects (e.g. software, see sections 7, 10.3) Subsystem

Qualitative aspects suitable up to PL: n/a

Documentation:

Document:

Electromagnetic immunity, EMI (Annex L) Subsystem

Route for fulfilment of EMI measures: The fulfilment of the measures for electromagnetic immunity (EMI) was documented in the associated safety function.

PL requirements: fulfilled

The PL shall be determined by the estimation of the following aspects (section 6.1.1):

- Behaviour of the safety function under fault conditions [fulfilled]
- Safety-related software according to clause 7 and Annex J or no software included [fulfilled]
- Systematic failure (see clause 6.1.7 and Annex G) [fulfilled]
- Ability to perform a safety function under expected environmental conditions [fulfilled]



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (pilot pressure)

Reached PL:	e	PFH [1/h]:	4,29E-8
-------------	---	------------	---------

Documentation:

Category Subsystem

Cat.:	3
-------	---

Category requirements:	fulfilled
------------------------	-----------

Requirements for the category:

- Accordance with relevant standards to withstand the expected influences. [fulfilled]
- Basic safety principles are being used. [fulfilled]
- Well-tries safety principles are being used. [fulfilled]
- A single fault tolerance and reasonable fault detection are given. [fulfilled]
- MTTFD is at least Low. [fulfilled]
- Requirement fulfilled because of the assumed limit value accuracy of 5 percentage points. [fulfilled]
- The achieved score of the CCF-rating is at least 65. [fulfilled]

Documentation:

Source (e.g. standard) Category:

File:

MTTFD and Mission time Subsystem

MTTFD [a]:	100 (High)
------------	------------

Mission time [a]:	20	Shortest mission time [a]:	20
-------------------	----	----------------------------	----

Diagnostic coverage Subsystem

DCavg [%]:	90 (Medium)
------------	-------------

Common cause failure Subsystem

CCF Points:	95 (fulfilled)
-------------	----------------

CCF Measures:

- 15 Points | Separation/segregation
- 20 Points | Diversity
- 15 Points | Protection against over-voltage, over-pressure, over-current, over-temperature
- 5 Points | Assessment/analysis
- 5 Points | Training
- 25 Points | Prevention of EMI or impurity of fluidic medium
- 10 Points | Other influences

Documentation:

Document:

Status / Messages Subsystem

Status:	green
---------	-------



Project name: 100402


File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (pilot pressure)**Channels / Test channels (1 / 2)****CH** Name: Channel 1

MTTFD [a]: 100

Blocks (1 / 1)**BL** Name: 5/3 Directional control valve, pilot valve**Reference designator:** Q2**Inventory number:***Device details Block***Device Manufacturer:****Device Identifier:****Device group:****Part number:****Revision:****Function:**☐ Input
☒ Output☐ Logic
☐ unknown**Technology:** unknown**Category:** -**Use case:****Description of the use case:***Documentation Block***Documentation:****Document:***MTTFD and Mission time Block***MTTFD [a]:** 380,5 (High)**Mission time [a]:** 20**Shortest mission time [a]:** 20**B10 [cycles]:** 10000000**RDF [%]:** 50**B10D [cycles]:** 20000000**nop [cycles/a]:** 525600**Documentation:****Document:***Diagnostic coverage Block***DC [%]:** 90 (Medium)**Measure:**

Indirect monitoring (e.g. monitoring by pressure switch, electrical position monitoring of machine actuators)



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (pilot pressure)

Documentation:

Document:

Status / Messages Block

Status: green

Channels / Test channels (2 / 2)

CH Name: Channel 2

MTTFD [a]: 100

Blocks (1 / 1)

BL Name: 3/2 Directional control valve

Reference designator: K1

Inventory number:

Device details Block

Device Manufacturer:

Device Identifier:

Device group:

Part number:

Revision:

Function:

☐ Input
☒ Output

☐ Logic
☐ unknown

Technology: unknown

Category: -

Use case:

Description of the use case:

Documentation Block

Documentation:

Document:


MTTFD and Mission time Block

MTTFD [a]: 91324,2 (High)

Mission time [a]:	20	Shortest mission time [a]:	20
-------------------	----	----------------------------	----

B10 [cycles]:	10000000	RDF [%]:	50
---------------	----------	----------	----

B10D [cycles]:	20000000	nop [cycles/a]:	2190
----------------	----------	-----------------	------



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (pilot pressure)

Documentation:

Document:

Diagnostic coverage Block

DC [%]: 90 (Medium)

Measure:

Indirect monitoring (e.g. monitoring by pressure switch, electrical position monitoring of machine actuators)

Documentation:

Document:

Status / Messages Block

Status: green

Subsystems (2 / 2)

SB Name: 5/3 Directional control valve, main stage with fault exclusion

Reference designator: Q2

Inventory number:

Device details Subsystem

Device Manufacturer:

Device Identifier:

Device group:

Part number:

Revision:

Function:

☐ Input

☒ Output

☐ Logic

☐ unknown

Use case:

Description of the use case:

Documentation Subsystem

Documentation:


Document:

Performance Level Subsystem

PL determination: Enter PL/PFH directly (manufacturer ensures compliance with the requirements of the Category and of the PL)

PL: d

Qualitative aspects (e.g. software, see sections 7, 10.3) Subsystem



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

SF Safety function: PUS (pilot pressure)

Qualitative aspects suitable up to PL: n/a

Documentation:**Document:***Electromagnetic immunity, EMI (Annex L) Subsystem*

Route for fulfilment of EMI measures: The fulfilment of the measures for electromagnetic immunity (EMI) was documented in the associated safety function.

Reached PL: d **PFH [1/h]:** 0.0E+0

Documentation:

PL e must not be based solely on fault exclusion (ISO 13849-1, 6.1.10.3), so that the maximum possible PL is limited to PL d.

Mission time [a]: 20 **Shortest mission time [a]:** 20

Category Subsystem

Cat.: 3

Category requirements: fulfilled

Requirements for the category:

Since the category is given by the manufacturer he is responsible to satisfy the requirements.

Documentation:

A category 3 only results from the external interruption and exhausting of the pilot air supply of the 5/3 directional control valve Q2 with valve K1.

Source (e.g. standard) Category:**File:***Status / Messages Subsystem*

Status: green



Project name: 100402

File date: 13.10.2026 12:44:52 Report date: 13.10.2026 Checksum: 42d2f621bc647e349fee673a2973a282

EXCLUSION OF LIABILITY

Care has been taken in production of the software SISTEMA, which corresponds to the state of the art. It is made available to users free of charge.

Die Haftung des Institut für Arbeitsschutz der DGUV (IFA) ist damit auf Vorsatz und grobe Fahrlässigkeit (§ 521 BGB) bzw. bei Sach- und Rechtsmängel auf arglistig verschwiegene Fehler beschränkt (523, 524 BGB).

The Institute for Occupational Safety and Health of the German Social Accident Insurance undertakes to keep its website free of viruses; nevertheless, no guarantee can be given that the software and information provided are virus-free. The user is therefore advised to take appropriate security precautions and to use a virus scanner prior to downloading software, documentation or information.

German Social Accident Insurance (DGUV)
Glinkastraße 40
D-10117 Berlin

E-mail: info@dguv.de
Internet: www.dguv.de

NOTE

This document is not a complete technical documentation according to EN ISO 13849-1:2023, clause 12.

CONTACT

Company contact details unknown

Name in block letters

Date, signature

Authors

Authors

Inspectors

Inspectors