

CERTIFICATE OF COMPLIANCE

Certificate Number 20160623-E232949
Report Reference E232949-20070320
Issue Date 2016-JUNE-23

Issued to: FESTO AG & CO KG
RUITER STR 82
73734 ESSLINGEN, GERMANY

**This is to certify that
representative samples of** PROXIMITY SWITCHES
See Addendum Page

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL508 & CSA-C22.2 No. 14, Industrial Control Equipment
Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160623-E232949
Report Reference E232949-20070320
Issue Date 2016-JUNE-23

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Models:

SIEN-M8B-PO-K-L, SIEN-M8B-PS-K-L, SIEN-M8B-NO-K-L, SIEN-M8B-NS-K-L, SIEN-M8B-PO-S-L, SIEN-M8B-PS-S-L, SIEN-M8B-NO-S-L, SIEN-M8B-NS-S-L, SIEN-M12B-PO-K-L, SIEN-M12B-PS-K-L, SIEN-M12B-NO-K-L, SIEN-M12B-NS-K-L, SIED-M12B-ZO-K-L, SIED-M12B-ZS-K-L, SIEN-M12B-PO-S-L, SIEN-M12B-PS-S-L, SIEN-M12B-NO-S-L, SIEN-M12B-NS-S-L, SIED-M12B-ZO-S-L, SIED-M12B-ZS-S-L, SIEN-M18B-PO-K-L, SIEN-M18B-PS-K-L, SIEN-M18B-NO-K-L, SIEN-M18B-NS-K-L, SIED-M18B-ZO-K-L, SIED-M18B-ZS-K-L, SIEN-M18B-PO-S-L, SIEN-M18B-PS-S-L, SIEN-M18B-NO-S-L, SIEN-M18B-NS-S-L, SIED-M18B-ZO-S-L, SIED-M18B-ZS-S-L, SIEN-M30B-PO-K-L, SIEN-M30B-PS-K-L, SIEN-M30B-NO-K-L, SIEN-M30B-NS-K-L, SIED-M30B-ZO-K-L, SIED-M30B-ZS-K-L, SIEN-M30B-PO-S-L, SIEN-M30B-PS-S-L, SIEN-M30B-NO-S-L, SIEN-M30B-NS-S-L, SIED-M30B-ZO-S-L, SIED-M30B-ZS-S-L, SIEN-M8NB-PO-K-L, SIEN-M8NB-PS-K-L, SIEN-M8NB-NO-K-L, SIEN-M8NB-NS-K-L, SIEN-M8NB-PO-S-L, SIEN-M8NB-PS-S-L, SIEN-M8NB-NO-S-L, SIEN-M8NB-NS-S-L, SIEN-M12NB-PO-K-L, SIEN-M12NB-PS-K-L, SIEN-M12NB-NO-K-L, SIEN-M12NB-NS-K-L, SIED-M12NB-ZO-K-L, SIED-M12NB-ZS-K-L, SIEN-M12NB-PO-S-L, SIEN-M12NB-PS-S-L, SIEN-M12NB-NO-S-L, SIEN-M12NB-NS-S-L, SIED-M12NB-ZO-S-L, SIED-M12NB-ZS-S-L, SIEN-M18NB-PO-K-L, SIEN-M18NB-PS-K-L, SIEN-M18NB-NO-K-L, SIEN-M18NB-NS-K-L, SIED-M18NB-ZO-K-L, SIED-M18NB-ZS-K-L, SIEN-M18NB-PO-S-L, SIEN-M18NB-PS-S-L, SIEN-M18NB-NO-S-L, SIEN-M18NB-NS-S-L, SIED-M18NB-ZO-S-L, SIED-M18NB-ZS-S-L, SIEN-M30NB-PO-K-L, SIEN-M30NB-PS-K-L, SIEN-M30NB-NO-K-L, SIEN-M30NB-NS-K-L, SIED-M30NB-ZO-K-L, SIED-M30NB-ZS-K-L, SIEN-M30NB-PO-S-L, SIEN-M30NB-PS-S-L, SIEN-M30NB-NO-S-L, SIEN-M30NB-NS-S-L, SIED-M30NB-ZO-S-L, SIED-M30NB-ZS-S-L, SIES-QB-PA-X-2L, SIEN-6,5B-PO-K-L, SIEN-6,5B-PS-K-L, SIEN-6,5B-NO-K-L, SIEN-6,5B-NS-K-L, SIEN-6,5B-PO-S-L, SIEN-6,5B-PS-S-L, SIEN-6,5B-NO-S-L, SIEN-6,5B-NS-S-L, SIES-QB-PO-K-L, SIES-QB-PS-K-L, SIES-V3B-PS-S-L, SIES-V3B-NS-S-L, SIEH-M12B-PO-K-L, SIEH-M12B-PS-K-L, SIEH-M12B-NO-K-L, SIEH-M12B-NS-K-L, SIEH-M12B-PO-S-L, SIEH-M12B-PS-S-L, SIEH-M12B-NO-S-L, SIEH-M12B-NS-S-L, SIEH-M18B-PO-K-L, SIEH-M18B-PS-K-L, SIEH-M18B-NO-K-L, SIEH-M18B-NS-K-L, SIEH-M18B-PO-S-L, SIEH-M18B-PS-S-L, SIEH-M18B-NO-S-L, SIEH-M18B-NS-S-L, SIES-Q40B-PA-X-2L, SRBG-C1-N-1-P-M12, SRBG-C1-N-1-ZU-M12, SRBG-C1-N-20N-ZC-M12-EX5, SRBG-C1-N-1-AS-M12-M12, SRBG-C1-N-1-P-C2-C2, SRBG-C1-N-1-ZU-C2-C2, SRBG-C1-N-20N-ZC-C2-C2-EX5



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

